9277

Diag. Cht. No. 5101-4

NOAA FORM 76-35A

U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

DESCRIPTIVE REPORT

(HYDROGRAPHIC)

Type of Survey HYDROGRAPHTC

Field No. H-9277

Office No. H-9277

LOCALITY

State CALIFORNIA

General Locality GULF OF SANTA CATALINA

Locality SOUTHWEST OF DANA POINT

19 72

CHIEF OF PARTY
G.E. Haraden

LIBRARY & ARCHIVES

6/24/77


ana 5

(14020) 5002 (1402) 5002 (18740) 5101 upplied 5142 applied

☆ U.S. GOV. PRINTING OFFICE: 1975—868-353

inhed

		· · · · · · · · · · · · · · · · · · ·
NOAA FORM 77-2 (11-72)	8 U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION	
ļ	HYDROGRAPHIC TITLE SHEET	н-9277
	HIDROGRAFAIC HILE SHEET	4-7211
INSTRUCTION	of the University of the Unive	FIELD NO.
	IS - The Hydrographic Sheet should be accompanied by this form, apletely as possible, when the sheet is forwarded to the Office.	
	apretery as possible, when the speet is forwarded to the Office.	■ RA- 4Ø-1A-72
State Ca	lifornia	
State	GULF OF SANTA CATALINA	
General loca		
	ling <u>Southern Galifornia</u> Southwest of Dana Point	
Locality	Galf-of Santa Catalina	
		W1 0 W 1 00 7000
Scale1:	List, signs Date of su	March 9 - March 28, 1972
	dated 7 January 1972 Project No.	OPR-411-RA-72
Instructions	dated Project No	
Vessel	NOAA Ship RAINIER	
Chief of a com	y CAPT Gerard E. Haraden	
Chief of part	LTJG Adams, LTJG Anderly, LTJG Franklin,	ENE Hollingheed IMIC McCohe
Surveyed by	LT Stubblefield	and nottimeneau, ning recorde,
1		
Soundings ta	ken by echo sounder, hand lead, pole McKiernan-Terry	PDR Mark XV Recorder Serial #321
Graphic recor	rd scaled by Ship's Personnel	
Graphic recor	d checked by Ship's Personnel	
Positions v	erified	
	Sandor Reher Automa	ated plot by FMC Xynetics Plotter
Soundings		
Verification	by Sandor Feher	
Soundings in	follows VVVV remove and Dothone o	4 MTTU
, ≥ómam8a m	fathoms X at XXX MLLW Fathoms a	C PILLIW
		The state of the s
	•	
REMARKS:	The Modified Transverse Mercator Projecti	on, soundings, and
_		
<u> </u>	position numbers on the boatsheet were pl	otted by the RAINIER's
	TTT 0/	
	PDP-8/e computer and COMPLOT plotter.	
[.		
	applied to state 11	10.04
	upplied to state !!	-19-77
		PH -



A. PROJECT

This survey was conducted in accordance with PROJECT INSTRUCTIONS: OPR-411-RA-72, dated 7 January 1972. Subsequent changes to these instructions are not applicable to this survey.

B. AREA SURVEYED

The boat sheet for H-9277 was divided into parts due to size limitations imposed by the onboard Hydroplot/Complot system. The eastern part of the sheet designated Field No. RA-40-1A-72, was initiated during this survey. See the Index to Survey Sheets in the Appendix for the relative position of this survey within the boat sheet.

The 1972 work on sheet H-9277, scale 1:40,000, covers an area southwest of Dana Point in the Gulf of Santa Catalina bounded by latitudes 33°08'N and 33° 21'N and longitudes 118° 02'W and 117° 51'W. The survey began on 9 March 1972 and was completed 28 March 1972.

C. SOUNDING VESSEL

Soundings on sheet H-9277 (RA-40-1A-72) were obtained by the NOAA Ship RAINIER. The soundings along regular lines are shown in black ink. The crosslines in red ink. All bottom samples are denoted on the boat sheet by green circles. The soundings on the boat sheet were plotted by the Complot Plotter in combination with the Digital Equipment Corporation PDP 8/e computer.

D. SOUNDING EQUIPMENT

The RAINIER used the McKiernan-Terry PDR Mark XVA Recorder Serial No. 324 in depths from 250-535 fathoms. There were no sounding equipment problems during the course of the survey which would have an adverse effect on the data.

Initial, fine arc, and phase corrections were unnecessary for the recorder used. The initial value was inspected continuously throughout the survey and adjusted as necessary. No abstract of initial corrections was

compiled since any difference in the initial value appeared only on the fathogram and not on the digitized record. In check scaning the fathogram, the initial value was taken into consideration. The PDR recorder used a stylus traveling in a straight line, thus fine arc corrections were unnecessary. Internal phase comparisons and necessary corrections were made so that all phase corrections would be at zero prior to any survey work.

E. SMOOTH SHEET

The boat sheet's Modified Transverse Mercator Projection and soundings were plotted by RAINIER personnel using the onboard PDP 8/e Complot System. The boat sheet was prepared using a central meridian of 118° 25' 00"W and a control latitude of 3,500,000 meters North. Position numbers and Hi-Fix arcs were also plotted by the computer and plotter. The final smooth sheet will be plotted by PMC's Electronic Data Processing Division.

The soundings and positions were originally plotted on time. During the survey, personnel kept track of lost Hi=Fix lanes and updated the position input data so as to read the correct whole lane values. Any errors subsequently observed were entered on a corrector tape and applied to the boat sheet. The positions on this sheet have also been corrected for the partial lane corrections resulting from 3-point sextant fix calibrations before and after each period of hydrography. An abstract of these corrections appear in the Separates following the text.

All soundings were digitized with draft (2.5 fathoms) and predicted tide corrections applied on time. The fathograms were later scanned for peaks and deeps and compared against printouts. All necessary corrections have been made.

A modified velocity correction, which incorporates instrument error, and velocity corrections were applied to the recorded depths through the Transducer Correction/Table Indicator (TC/TI) tape. However, these TC/TI corrections have not been applied to soundings appearing on the boat sheet. Velocity corrections were

computed from a Nansen Cast taken at latitude 33° 18.9'N longitude 117° 44.6'W on 17 March 1972, and are shown in the Separates. For further information on all corrections refer to Corrections to Echo Soundings, OPR-411. NOAA Ship RAINIER, 1972.

F. CONTROL

Decca Hi-Fix was used for horizontal control and was operated in the hyperbolic mode on Type A moderate power, transmitting on 1799.6 KHz. The stations operated satisfactorily and caused no problems during the survey.

The master station was located on a 40 foot bluff, 0.23 miles from the shoreline overlooking a flat, sandy and grassy plain. A 35 foot whip antenna was erected (latitude 33° 43' 12.946"N, longitude 118° 16' 56.980"W) adjacent to R.M. 1 of triangulation station OLD, 1899. The master station was within the confines of Fort Mc-Arthur Army Reservation, San Pedro, California.

Slave station I was established atop a rounded hill on Santa Catalina Island, California. A 35 foot whip antenna was erected over traverse station, HI FIX, 1972 (latitude 33° 21' 25.309"N, longitude 118° 21' 50.721"W) at an elevation of approximately 1525 feet, 1.4 miles from the shoreline. No topographic obstruction of consequence was between slave station 1 and the survey area. The hyperbolic arcs generated by the master station and slave station 1 were drawn on the boat sheet with green ink.

Slave station 2 included a 35 foot whip positioned over triangulation station TEMPORARY, 1972 at an approximate elevation of 45 feet. The station was 0.30 miles from the shoreline overlooking a sandy beach in latitude 33° 14' 57.267"N and longitude 117° 25' 28.755"W. The hyperbolic rates created by the master station and slave station 2 were shown on the boat sheet in red ink.

The Hi-Fix receiver on the RAINIER was calibrated at the beginning and end of each day's work. The calibration was accomplished by visual three-point sextant fixes on previously established geodetic positions of natural or hand fabricated objects. A mathematical solution for three-point fixes was obtained by using program AM 560 in the PDP 8/e computer.

Adverse visibility conditions from fog occasionally precluded obtaining a visually established position and necessitated utilizing a buoy for calibration. Each day the calibration buoy was employed, a sextant fix was obtained at some other time during the day. These invariably offered calibration values which agreed with those obtained from visual fixes. It is to be emphasized that the buoy was utilized for Hi-Fix calibration only when it was impossible to observe the visual signals. For additional information on Hi-Fix control refer to the Hi-Fix Report, OPR-411, NOAA Ship RAINIER, 1972. See separates for a list of Hi-Fix correctors.

G. SHORELINE

There is no shoreline shown since this was entirly an offshore survey.

H. CROSSLINES

Crosslines on sheet H-9277, RA-40-1A-72, totaled 69 nautical miles or 12.6% of the total miles run. There is excellent agreement between main scheme and crossline soundings. Approximately 90% of the soundings agree within one fathom, and balance agrees within 2-4 fathoms. Most of the soundings disagreeing by 2-4 fathoms are located in the southeast corner of the boat sheet where there is rugged bottom relief.

I. COMPARISON WITH JUNCTION SURVEYS

Survey H-9277 junctions with the following surveys:

Registry	No.	Scale	Year	Color on boat sheet
H-9253		1:40,000	1971	blue
H-9253		1:40,000	1972	lime
H-9114		1:40,000	1970	carmine
H-9113		1:40,000	1970	brown

Survey H-9277 agrees well with H-9253. About 90% of the soundings agree to within one fathom, with the remaining 10% of the soundings agreeing to within two fathoms. The few available soundings from H-9113 and H-9114 agree well with this survey.

J. COMPARISON WITH PRIOR SURVEYS

Comparison with prior survey H-6118, 1:80,000, 1935 reveals a greater disparity than with the more modern surveys. Approximately 33% of the soundings agree within one fathom, 22% within 2-4 fathoms, 25% within 4-8 fathoms, 16% within 8-12 fathoms and 4% differ by about 20 fathoms. The greatest differences are in an area of rugged bottom relief at the SE corner of the survey. Considering the superior sounding and positioning techniques used in this survey, compared to those used in 1935, the 1972 depths are considered the more correct and should be used for charting.

K. COMPARISON WITH THE CHARTS

This survey was compared with charted soundings on Charts 5101 (15th Ed. 2/71) and 5142 (9th Ed. 4/71). Charted soundings are deeper in both cases with the greatest disparity on 5101. Approximately 20% of the charted soundings on 5101 are 15-17 fathoms deeper than observed on this survey. One sounding at 33° 16' 30"N, 117° 57' / 30"W is 28 fathoms deeper.

Chart 5142, being a more recent chart, shows much better agreement with 95% of the soundings 0-4 fathoms deeper and the remainder 4-6 fathoms deeper.

The 1972 soundings should be considered more correct and supercede older soundings for charting.

L. ADEQUACY OF SURVEY

The survey is considered adequate for charting to the extent of its completion.

M. AIDS TO NAVIGATION

No aids to navigation exist in the H-9277 survey area.

N. STATISTICS

Sheet H-9277, RA-40-1A-72 contains 60% positions, 368.1

nautical miles of sounding lines, approximately 69 square nautical miles of survey area, and six bottom samples.

DATA PROCESSING

All data was obtained using the on-line plot program, AM 100, in conjunction with the PDP 8/e Hydroplot system. This program plots soundings and positions in real time and provides a punched paper tape in the master format with a teletype listing of all hydrographic data collected.

Corrector tapes were prepared using the standard Hydro-plot/Hydrolog corrector tape format for all peaks, deeps, sounding and control changes.

For further information on data processing see PDP 8/e Hydroplot/Hydrolog Systems Report, OPR-411, NOAA Ship RAINIER, 1972

REFERENCES TO REPORTS

- Corrections to Echo Soundings, OPR-411, NOAA Ship RAINIER, 1972.
- 2. Hi-Fix Report, OPR-411, NOAA Ship RAINIER, 1972 PDP 8/e Hydroplot/Hydrolog Systems Report, OPR-411,
- NOAA Ship RAINIER, 1972
 4. <u>Tide Report</u>, OPR-411, NOAA Ship RAINIER, 1972
 5. <u>Descriptive Report to Accompany H-9253 (RA-40-3-71)</u>, OPR-411, NOAA Ship RAINIER, 1971

Respectfully submitted,

Robert L. Johnson

LTjg, NOAA

APPROVAL SHEET

H-9277 (RA-40-1A-72)

9 March - 28 March 1972

Gulf of Santa Catalina, California

In producing this sheet, standard hydrographic procedures were observed and the data was examined daily during the execution of the survey.

The boat sheet and accompanying records have been examined by me and are considered complete and adequate to the extent of this survey, and are approved. Note that further work is necessary for the completion of H=9277.

HE Haraden G.E. Haraden CAPT, NOAA


LIST OF SIGNALS

OPR-411

022	DAY BEACON AND LIGHT #1	33	27	15.64	117	41	26.38
028	DANA PT. MARINA B.P. A	33	27	28.06			11.52
029	DANA PT. MARINA B.P. B	33	27	25.03			58.33
030	DANA PT. MARINA B.P. C			20.80			40.36
510	OCEANSIDE SE ENT LT			21.10			55.44
517	CAMP DELMAR S GROIN LT			49.42			04.75
523	VORTAC			26.15	117	25	00.65
701	MEDIO			59.19			01.00
703	SAN ONOFRE WATER TANK			15.87			31.32
705	AIRWAY NO. 5	33	23	17.53			40.88
707	COTTON 2			52.53			56.92
80i	SAN MATEO ROCK						59.05
803	SAN JUAN ROCKS (HIGHEST)	33	27	25.61	117	42	46.08

VELOCITY CORRECTOR TABLE #10 RA-40-1-72

Depth		Corr	Š			
000045	Ø	0000	0010	000	000000	000000
000080	Ø	0001				
000150	Ø	0002				
000250	Ø	0004		141		
000350	Ø	0006				
000460	Ø	0008				
000580	Ø	0010				
000705	Ø	ØØ12				
000830	Ø	0014				
000965	Ø	0016				
001095	Ø	0018			1. 4. 7. 24.	
001225	Ø	0020				
001685	Ø	0025				
002200	Ø	0030				
003000	Ø	0040				
003800	Ø	0050				
004700.	Ø	0060				
005600	Ø	0070				



TIDE NOTE

H-9277 (RA-40-1-72)

It is recommended that the tide station at San Diego, California in latitude 32° 42.8'N and longitude 117° 10.4'W, be used to control the soundings on this survey. This gage operated on Time Meridian 120°W. Hourly heights and time and height differences will be furnished by the Tides Branch in Rockville.

Predicted tides for the boat sheet were obtained from the Tide Tables, 1972, North American Coast using the Point Loma Subordinate Station. The tides were applied directly to the data when plotted by the computer.

U. S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL OCEAN SURVEY

TIDE NOTE FOR HYDROGRAPHIC SHEET

2/28/73

Processing Division: Pacific Marine Center

Hourly heights are approved for

Tide Station Used (NOAA form 77-12): San Diego, California

Period: March 1972

971 1972

HYDROGRAPHIC SHEET: H-9248, H-9277)_

OPR: 411

Locality: San Diego, California

Plane of reference (mean lower low water): 3.5 ft.

Height of Mean High Water above Plane of Reference is 5.0 ft.

Remarks: Zoning instructions. Use San Diego hourly heights direct.

Chief, Tides Branch

Survey No.			135	133	13 5	· / ;5°	رة من المراجعة	/ ;: ō'''	`/ ^ri.`	<i>"/</i>
н-9277		12 OF	Clerk,	39.5%	S. R. S.		C. C. L.	Hos High	7. 2. L.	
Name on Survey	A OF	B 8	C C	St.	E	onici ¹	G	Н	ν. κ	
GULF OF SANTA CATALINA	х									
	****					<u> </u>				
					:			,		ļ.
										†
	,									†
										+
										+
		ļ					<u> </u>	<u> </u>		+
			 	<u> </u>						+
										+
			 							1 1
			<u> </u>							+
										+'
			<u> </u>							
			ļ		<u> </u>					
			 			ļ				1,
			<u> </u>	<u> </u>			OVED			1.
						s. E.	Han	-		1
					S	AFF GE	DGRAPH	ER 2	51×2	2
						15 A	ug. 19	17		2
							7			2
										2
										2
										2
							-			2

HYDROGRAPHIC SURVEY STATISTICS HYDROGRAPHIC SURVEY NO. H-9277

RECORDS ACCOMPANYING SURVEY: To be completed when survey is registered.

RECOF	RD DESCRIPTION	АМО	UNT		RECORD DESC	AMOUNT		
	with smooth F			1	BOAT S	HEETS (Pape	er)	1
DESCRIPTIVE R				1	OVERL	ays (preli	minary)	4
DESCRIPTION	DEPTH RECORDS	HORIZ.	CONT.	PRIN	routs	TAPE ROLLS	PUNCHED CARDS	ABSTRACTS/ SOURCE DOCUMENTS
ENVELOPES				1- Smo				
AHIERS	Printouts, PDR faths.							Brush Recordings
' VOLUMES	1*							
BOXES								

T-SHEET PRINTS (List)

not recieved at registration 6/24/77 MCR

N/A

SPECIAL REPORTS (List)

N/A

OFFICE PROCESSING ACTIVITIES

The following statistics will be submitted with the cartographer's report on the survey

	AMOUNTS						
PROCESSING ACTIVITY	PRE- VERIFICATION	VERIFICATION	REVIEW	TQTALS			
POSITIONS ON SHEET				6ø3			
POSITIONS CHECKED		6ø3					
POSITIONS REVISED		3					
DEPTH SOUNDINGS REVISED		34					
DEPTH SOUNDINGS ERRONEOUSLY SPACED		° ø					
SIGNALS ERRONEOUSLY PLOTTED OR TRANSFERRED	D	ø		<u></u>			
	TIME (MANHOURS)						
Verification of Control		11					
Verification of Positions		22					
Verification of Soundings		41					
Smooth Sheet Compilation),),					
ALL OTHER WORK		1Ø					
TOTALS		128					
PRE-VERIFICATION BY James S. Green		BEGINNING DATE 1/17/74 BEGINNING DATE	1	G DATE /17/74 G DATE			
Sandor A. Feher		12/6/76 BEGINNING DATE	1/	2Ø/77			
Q.C. Insp Rw. Herkazarian 23	.hrs	BEGINNING DATE	1 ;	2/17			

Insp Rw. Herkazarian 23hr

10/20/17

Barn (astru 4)173 2-27/439 REG. #6

The Computer and Excess Sounding Cards for this survey have not been corrected to reflect the changes made to the Computer Card and Excess Card Printouts at this time of the review.

When the cards have been updated to reflect the final results of the survey the following shall be completed:

CARDS CORRECTED

Reg. No.	
	
e containing the data rected to reflect the n and review. c tape has been updat the survey, the foll	e changes made
MAGNETIC TAPE CORREC	CTED
TIME REQ'D.	INITIALS
3	n and review. c tape has been update the survey, the foll MAGNETIC TAPE CORREC

H-9277

Information for Future Presurvey Reviews

No noteworthy items for a future Presurvey Review fall within the limits of this survey.

Position Index	Bottom Change	Use	Resurvey
Lat. Long.	Index	<u>Index</u>	Cycle

This survey is centered in latitude $33^{\circ}10^{\circ}$, longitude $118^{\circ}00^{\circ}$ and has all depths in excess of 20 fathoms and is on a 50-year resurvey cycle.

PACIFIC MARINE CENTER VERIFIER'S REPORT

REGISTRY NO: H-9277

FIELD NO: RA-4Ø-1A-72

California, Gulf of Santa Catalina, Southeast of Santa Catalina Island

SURVEYED: 9 March - 28 March 1972

PROJECT NO: OPR-411-RA-72

SCALE: 1:40,000

SOUNDINGS: McKiernan-Terry

PDR Mark XV Recorder

CONTROL: Decca Hi-Fix

Surveyed by......LTJG Adams, LTJG Anderly,
LTJG Franklin, ENS Hollinshead,

LTJG M6CABE, LT Stubblefield

Automated Plot by.......PMC Xynetics Plotter

May 2, 1977

I. INTRODUCTION

This is a basic offshore survey accomplished by the RAINTER, MSS-21, from March 9 to March 28, 1972. The area surveyed is off the southern California coast, southeast of Santa Catalina Island, in the Gulf of Santa Catalina. This survey was not completed during the 1972 field season and has been carried as incomplete since then. As there is no apparent intention to complete this survey in the foreseeable future, the data has been processed at this time to make it available for charting. If offshore survey work is scheduled for this part of California in the future, the existing survey sheet limits in this area should be revised to attain a junction with the 1972 data.

The smooth sheet plotting parameters, station list and sounding correctors (except for tides) are included with the position and sounding printouts. The tide correctors are included in the cahier with the raw sounding records.

II. CONTROL AND SHORELINE

Control for this survey is adequately covered in Section F of the Ship's Report and the OPR-411-RA-72 Hi-Fix Report.

As this is an offshore survey, there are no shoreline manuscripts.

III. HYDROGRAPHY

Crosslines agree with the main scheme hydrography very well, generally within a fathom. The basic hydrography is adequate to delineate the bottom configuration and to determine least depths. See Q.C. Report

IV. CONDITION OF SURVEY

The hydrographic records, overlays, smooth sheet, and reports are adequate and conform to the requirements of the Provisional Hydrographic Manual.

V. JUNCTIONS

An adequate junction was effected to the southhwith prior survey H-9113, $\approx 1.4\emptyset, \emptyset\emptyset\emptyset$ (1970).

At southwest portion of the sheet, junction was made with prior survey H-9114, 1:4 \emptyset , $\emptyset\emptyset\emptyset$ (197 \emptyset).

At the east and north, an adequate junction was effected with $\frac{prior}{1}$ survey H-9253, 1:40,000 (1971).

adequate
An effective junction was made with H-9508, 1:20,000 (1975) on the northwest portion of the survey. The brown, 350 fathom supplementary curve was extended from H-9508 to show continuity between junctions.

This survey is incomplete west of 118° Ø2"W longitude and, therefore, provides no contemporary data for effecting junction.

Soundings and depth curves are in good agreement and the junction notes are inked accordingly.

See Q.C. Report

VI. COMPARISON WITH PRIOR SURVEYS

н-6118 (1935), 1:8ø,øøø

Generally the depths agree to within 12 fathoms. This disparity is probably due to the more accurate positioning and sounding systems of the modern survey. H-9277 is adequate to supersede H-6118 for the area of common coverage.

There are no pre-survey review items for this survey.

See Q.C. Report

VII. COMPARISON WITH CHARTS

This survey was compared with Chart 51Ø1, 15th Edition, February 1971. The charted hydrography for the area of this survey generally originates from H-6118. This survey is adequate to supersede the charted hydrography for the area of common coverage.

See Q.C. Report

VIII. COMPLIANCE WITH PROJECT INSTRUCTIONS

This survey adequately complies with the project instructions, dated January 7, 1972.

IX. ADDITIONAL FIELD WORK

Additional field work is not required for the area covered by this survey. When offshore work is scheduled for this area in the future, a junction to the west of this survey should be accomplished.

This is a good basic survey, adequate to supersede the prior survey and to be the source of charted hydrography.

X. NOTES TO THE COMPILER

This survey was verified and the smooth sheet compiled by Sandor A. Feher, a verifier trainee, under my supervision.

Respectfully submitted,

Richard D. Lynn

Team Leader/Cartographic Technician

Richard D. Lynn

May 2, 1977

Examined and approved,

James S. Green

Chief, Verification Branch



U.S. DEPARTMENT OF COMMERCE
National Oceanic and Atmospheric Administration
NATIONAL OCEAN SURVEY, Pacific Marine Center
1801 Fairview Ave. E., Seattle, WA 98102

Date: 8 June 1977

To: Eugene A. Taylor, RADM

Director, PMC

From:

Chief, Processing Division

Subject: PMC Hydrographic Survey Inspection Team Report, H-9277

This is a basic hydrographic survey of an offshore area in the Gulf of Santa Catalina, CA. The survey was conducted by NOAA Ship RAINIER in 1972 in accordance with Project Instructions OPR-411-RA-72 dated Ø7 January 1972.

This survey is complete within the limits of hydrography but incomplete relative to the survey sheet layout. Since no efforts have been made to complete this survey since 1972 and since the OPR-411 project limits have subsequently been redefined to include, for the most part, only areas with depths less than 110 fathoms, there is little reason to believe that the survey sheet will be completed in the foreseeable future. Consequently, H-9277 has been processed as a complete survey of a limited area.

This is a straight-forward deep water survey. The inspection team has no substantive comments to add to the foregoing reports.

The inspection team finds survey H-9277 to be a very good survey, adequate for charting and to supersede the common area of the prior survey. Administrative approval is recommended.

Donald E. Nortrup, ICDB/

John C. Albright, LCDR

Dean R. Seidel, LCDR

A. E. Eichelberger





ADMINISTRATIVE APPROVAL H-9277

The smooth sheet and reports of this survey have been examined and the survey is adequate for charting and to supersede common areas of prior surveys.

Eugene A. Taylor, RADM

Director

Pacific Marine Center

UNITED STATES DEPARTMENT OF COMMERCE National Oceanic and Atmospheric Administration

NATIONAL OCEAN SURVEY Rockville, Md. 20852

C352

September 12, 1977

a & Patril

T0:

A. J. Patrick

Chief, Marine Surveys Division

THRU:

Chief, Quality Control Branch

FROM:

R. W. Derkazarian &w. Derkazarian

Quality Evaluator

SUBJECT:

Quality Control Report for H-9277 (1972), Southwest of Dana

Point, Gulf of Santa Catalina, California

Survey H-9277 was inspected to evaluate the accuracy and adequacy of the survey with respect to data acquisition, delineation of the bottom, determination of least depths, navigational hazards, junctions, sounding line crossings, smooth plotting, decisions and actions taken by the verifier, and the cartographic presentation of data. In general, it was found to conform to the National Ocean Survey's standards and requirements except as follows:

1. Under "Hydrography" in the Verifier's Report a statement was not made as to the adequacy of the delineation of the depth curves.

The usual depth curves are adequately delineated.

The supplemental brown curves have been added at 50-fathom increments to coincide with current charting practices.

- 2. The "Hydrographic Surveys Statistics" sheet indicated the present survey has one sounding volume. This volume was not forwarded to Headquarters.
- 3. The junctions with H-9113 and H-9114 of 1970 and H-9508 of 1975 were adequately completed during the quality evaluation; several curves have been adjusted and soundings transferred.
- 4. This information should be noted under the comparison with prior survey H-6118 (1935), 1:80,000.

A comparison between prior and present depths reveals differences of 6 to 12 fathoms in depths of 300 to 500 fathoms which probably are due



to less accurate methods of surveying on the prior survey. Several bottom characteristics have been carried forward to supplement the present survey. The 457-fathom sounding in latitude 33°17.4', longitude 117°58.8' and the 469-fathom sounding in latitude 33°16.46', longitude 117°58.00' fall in depths of 433-438 fathoms and 446 fathoms respectively on the present survey and are considered discredited.

With these additions the present survey is adequate to supersede the prior survey in the common area.

5. The verifier did not indicate that a comparison with chart 5142, 9th edition, latest print date April 1971, had been made. A portion of the present survey falls within the limits of that chart. See Provisional Hydrographic Manual section 6.3.10.

The charted hydrography of chart 5142 originates with the prior survey discussed in paragraph VI of the Verifier's Report and paragraph 4 above which require no further consideration.

Attention is directed to the following:

Chart 5101


The <u>432-fathom sounding</u> charted in latitude 33°07.0', longitude 117°54.00' originates with prior survey H-4505 (1925) as 482 fathoms and has been improperly charted. The charted sounding should be deleted.

The <u>366-fathom sounding</u> charted in latitude 33°07.30', longitude 117°57.8' originates with the uncorrected sounding of the boat sheet of H-9113 (1970), Bp-79061, and should be deleted from the chart.

The present survey is adequate to supersede the charted hydrography within the common area.

6. The Hydrographic Inspection Team did not indicate their time on the "Hydrographic Survey Statistics" sheet.

cc: C351



NAUTICAL CHART DIVISION

RECORD OF APPLICATION TO CHARTS

FILE WITH DESCRIPTIVE REPORT OF SURVEY NO. _

9277

INSTRUCTIONS

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart.

1. Letter all information.

2. In "Remarks" column cross out words that do not apply.

3. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.

CHART DATE CARTOGRAPHER PARTIES REMARKS [8774 3/4/78 CL. Kulle Full Per Belove After Verification Review Inspection S	
ATT 1 11478 Val. 1 1/200 Full Day Defeat After Verification Parism Town in	
	igned Via
Drawing No. COUFERN BY COTT CLAS	MOT
Drawing No. FULL TEPPETERS TO THE STATE OF T	BINK
5142 2-28-78 Hamilton Full Parties After Verification Review Inspection S	igged Vie
(18746) Drawing No. Rev RKR 3/28/28	igned via
1	
18774 3/1/78 Onlkile Full After Verification Review Inspection S.	
18774 3/1/78 Chile Full After Verification Review Inspection S.	igned Via
Drawing No. Fully MPPO THEM CHT	5742
1 Issued to the section of the secti	gned Via
(S101) 4-17-79 ROS Drawing No.	
18022 5-9-79 Hamilton Full Partier After Verification Review Inspection Si	gned Via
(5020) 5-17-79RCS Drawing No. 40	
	·
8020 6-25-71 Ham, Full Part Before After Verification Review Inspection Si	ened Via
5002) Drawing No. 32 they cht 18022	5
1-17-8/RX	
Full Part Before After Verification Review Inspection Si	oned Via
Drawing No.	gired VIA
Full Part Reform After Verification D	
Full Part Before After Verification Review Inspection Signature Drawing No.	ned Via
Diaming No.	· ,
Full Days D. C. and T. and T.	
Full Part Before After Verification Review Inspection Sig	ned Via
Drawing No.	
Full Part Before After Verification Review Inspection Sig	ned Via
Drawing No.	
·	
·	
	